

## Annexure D

## BUILDING SAFETY CERTIFICATE

No

63

Dated. 24.06.2025

It is certified that the existing building **Pt. Deendayal Upadhyay Saraswati Vidya Mandir inter College CBSE** at Gata No- 127 Vill- Udaypur Mahewa Pargana – Lakhimpur Kheri Tehsil- Lakhimpur Kheri Distt. -Lakhimpur- Kheri (UP) is having block(s)/Floor(s) as per details below.

Detail of Block(s) in school	Block (1) (School Building)	Block (2) (Office Block)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 03	NA	NA	NA	NA	NA

The building is owned/occupied by **Pt. Deendayal Upadhyay Saraswati Vidya Mandir inter College CBSE** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Rural Engineering Department** on 23.06.2025 in the presence of Mr. Ravi Bhushan Sahni S/O Mr. Bhagirath Ram Sahni, Gata No- 127 Vill- Udaypur Mahewa Pargana – Lakhimpur Kheri Tehsil- Lakhimpur Kheri Distt. -Lakhimpur- Kheri (UP) and that the building/premises is fit for occupancy for running school with effect from 23.06.2025 for a period of **Five Years** in accordance with rule and subject to compliance of the specific conditions as appended.

- 4- If intensity of earthquake in this region occurs more than 06.00 on reactor scale this certificate become invalid, inspection of building should be done again.
- 5- If No's of floor is increased then this certificate becomes invalid.
- 6- Proper maintenance should be done as per building by-laws and the national building code by the organization.

Issued on 24.06.25 at Lakhimpur by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : \_\_\_\_\_

*Ravi Shankar Shrivastava*

Name : रवि शंकर श्रीवास्तव

Designation : सहायक अभियन्ता

ग्रामीण अभियन्तण विभाग

प्रखण्ड-लखीमपुर-खीरी

Name & Address of Department/ Office: \_\_\_\_\_